





















Manual for  
452.04051/  
452.04057


**STEEL****EN**  
METAL DESIGN & EQUIPMENT





Tips:

- 1.Avoid bumping and destroying the surface layer when using.
- 2.Avoid violent opening and closing of doors or drawers.
- 3.Wipe with a soft cotton (dip with water if necessary), and do not use acid or alkaline detergents for cleaning.

A×1		B×1		C×1		D×1		
								
E×1		F×1		G×1				
								
				H×1				
								
I×1		J×1		L×4				
								
	N×43	O×4	P×4	Q×16	R×2	S×4	T×1	U×2
								Standby Application 






1



O×4


P×4

2




N×8

3




N×4

4




5





N×4

6









N×4

7



N×7



8





Q×16

9

If the spring shaft is lost, spare parts U can be used.




F




1

2



S




R×1



S×2

10


If the spring shaft is lost, spare parts U can be used.



2




E




S

1





R



R×1

S×2


11





LEGS NOT INCLUDED

N×16

12



The key is here



T×1

LEGS NOT INCLUDED